

Material Groups

Recommended Machining Conditions

ISO	Material	Condition	Tensile Strength [N/mm²]	Hardness HB	Mtl. No	Vc m/min	SUMOCHAM											
							Feed vs. Drill Diameter											
							D=4-4.9	D=5-5.9	D=6-7.9	D=8-9.9	D=10-11.9	D=12-13.9	D=14-15.9	D=16-19.9	D=20-25.9	D=26-32.9		
P	non-alloy steel and cast steel, free cutting steel	<0.25% C	annealed	420	125	1	80-110-140	0.04 0.06 0.08	0.07 0.09 0.11	0.09 0.11 0.13	0.12 0.17 0.22	0.15 0.21 0.28	0.18 0.24 0.30	0.20 0.27 0.35	0.25 0.35 0.45	0.25 0.35 0.50		
		≥0.25% C	annealed	650	190	2	80-105-130											
		<0.55% C	quenched and tempered	850	250	3	80-100-120											
		≥0.55% C	annealed	750	220	4	70-90-110											
	low alloy and cast steel (less than 5% of alloying elements)	quenched and tempered	quenched and tempered	1000	300	5	50-70-90											
P			annealed	600	200	6	80-100-120	0.04 0.06 0.08	0.07 0.10 0.13	0.09 0.12 0.15	0.12 0.18 0.25	0.14 0.21 0.28	0.16 0.24 0.32	0.18 0.26 0.35	0.23 0.31 0.40	0.25 0.35 0.50		
			annealed	930	275	7	70-90-110											
P			annealed	1000	300	8	50-70-90											
			annealed	1200	350	9	40-55-70											
P	high alloyed steel, cast steel and tool steel	annealed	680	200	10	50-70-90	0.06 0.07	0.07 0.09	0.09 0.11	0.12 0.16	0.12	0.15	0.18	0.20	0.22	0.25		
		quenched and tempered	1100	325	11	40-60-80												
P	stainless steel and cast steel	ferritic / martensitic	680	200	12	40-55-70	0.05 0.06	0.06 0.07	0.08 0.09	0.10 0.12	0.12	0.14	0.16	0.16	0.18	0.20		
		martensitic	820	240	13	40-55-70												
M	stainless steel and cast steel	austenitic, duplex	600	180	14	30-50-70	0.05 0.06 0.07	0.06 0.07 0.08	0.08 0.09 0.10	0.10 0.12 0.15	0.12 0.15 0.18	0.14 0.17 0.20	0.16 0.20 0.24	0.16 0.21 0.26	0.18 0.24 0.30	0.20 0.27 0.35		
K	gray cast iron (GG)	ferritic / pearlitic		180	15	90-125-160	0.04 0.06 0.08	0.10 0.13 0.15	0.12 0.15 0.22	0.15 0.20 0.30	0.20 0.25 0.35	0.30 0.35 0.45	0.35 0.35 0.45	0.40 0.40 0.55	0.40 0.40 0.60			
		pearlitic / martensitic		260	16	80-110-140												
K	nodular cast iron (GGG)	ferritic		160	17	90-135-180												
		pearlitic		250	18	80-110-140												
K	malleable cast iron	ferritic		130	19	90-125-160												
		pearlitic		230	20	80-110-140												
N	aluminum-wrought alloys	not hardenable		60	21	90-155-220	0.05 0.12 0.2	0.1 0.17 0.25	0.15 0.22 0.30	0.20 0.30 0.40	0.30 0.35 0.50	0.35 0.40 0.60	0.45 0.50 0.75	0.50 0.55 0.75				
		hardenable		100	22													
	aluminum-cast alloys	not hardenable		75	23													
		hardenable		90	24													
	>12% Si	high temperature		130	25	80-120-160												
S	>1% Pb	free cutting		110	26	90-155-220	0.05 0.12 0.2	0.1 0.17 0.25	0.15 0.22 0.30	0.20 0.30 0.40	0.30 0.35 0.50	0.35 0.40 0.60	0.45 0.50 0.70	0.50 0.55 0.75	0.50 0.55 0.75			
		brass		90	27													
	copper alloys	electrolytic copper		100	28													
S	high temperature alloys	Fe based	annealed	200	29	30-45-60	0.03 0.04 0.05	0.04 0.05 0.06	0.05 0.06 0.07	0.06 0.08 0.11	0.10 0.12 0.13	0.12 0.15 0.15	0.12 0.15 0.18	0.12 0.16 0.20	0.14 0.18 0.22	0.16 0.20 0.25		
		hardened		280	30													
		annealed		250	31													
	titanium alloys	hardened		350	32													
		cast		320	33													
H	hardened steel	pure		4														